Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1		702/85.ccls. and (remote near calibrating\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/01 14:02
L2	0	455/130.ccls. and (remote near calibrating\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/01 14:02
L3	0	455/63.3.ccls. and (remote near calibrating\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/01 14:03
L4	1	455/67.13.ccls. and (remote near calibrating\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/01 14:03
S1	199	702/85.ccls. and calibrating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/01 14:02
S2	2	"6091281".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/25 12:14
S3	2	"5764048".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:39
S4	6	455/130.ccls. and calibrating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:40
S5	1	455/63.3.ccls. and calibrating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:41

S6	7	455/67.13.ccls. and calibrating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:59
S7	0	remote near calibrating near measuring near instrument	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:59
S8	1883	remote and calibrating and measuring and instrument	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:00
S9	621	(remote and calibrating and measuring and instrument) and converting	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:08
S10	478	((remote and calibrating and measuring and instrument) and converting) and standard	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:08
S11	474	(((remote and calibrating and measuring and instrument) and converting) and standard) and reference	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:08
S12	1244	(remote and calibrating and measuring and instrument) and frequency	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:09
S13	366	((remote and calibrating and measuring and instrument) and converting) and (((remote and calibrating and measuring and instrument) and converting) and standard) and ((((remote and calibrating and measuring and instrument) and converting) and standard) and reference) and ((remote and calibrating and measuring and instrument) and frequency)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:09
S16	75	(remote near calibration) and standard and frequency	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/03/21 16:12

S17	561	satellite with calibration	US-PGPUB; USPAT; EPO; JPO; DERWENT;	OR	ON	2005/03/21 16:12
S18	13	S17 and (remote with sense)	IBM_TDB US-PGPUB; USPAT; EPO; JPO; DERWENT;	OR	ON	2005/03/22 10:06
S19	2	"20040215412"	IBM_TDB US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/25 16:27
S20	500	NIST and frequency and standard and calibration	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/25 12:14
S21	51	S20 and (optical near path)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/25 12:15
S32	358	702/85.ccls. and calibration\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/06 11:42
S33	161	702/85.ccls. and calibration\$4 and frequency	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/06 11:22
S34	4	702/85.ccls. and (remote near calibration\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/06 11:23
S35	1	455/130.ccls. and (remote near calibration\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/06 11:23

S36	0	455/63.3.ccls. and (remote near calibration\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/06 11:23
S37	2	455/67.13.ccls. and (remote near calibration\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/06 11:23
S38	1	702/188.ccls. and (remote near calibration\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/06 11:42
S39	1	702/189.ccls. and (remote near calibration\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/06 11:43
S40	1	((remote near calibration\$4) and converting\$4 and transmitting\$4 and reference and (physical near standard)).CLM.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/17 12:09
S41		((remote near calibration\$4) and converting\$4 and transmitting\$4 and reference and (physical near standard))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/17 12:17
S42	43	((remote near calibration\$4) and converting\$4 and transmitting\$4 and reference)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/17 12:18
S43	32	((remote near calibration\$4) and converting\$4 and transmitting\$4 and reference and standard)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/17 12:19

S44	169229	han.in.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/21 09:47
S45	3	S44 and (remote near calibration)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/21 09:47